



2319-0024



2319-0014

○ = wear parts

* = with SpiralClean in leakage chamber

